Continued: Consumer Interview and Vehicle Inspection, ODI 10189655



Photo 15: Driver all weather mat removed from vehicle



Photo 16: Driver inboard mat retention hook engaged in floor material



11 of 11